

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 018 Const Calendar Day: 182 Date: 09-Mar-2010 Tuesday

Inspector Name: Daouk, Sami Title:

Inspection Type: Continuous

Shift Hours: 07:00 am 05:30 pm **Break**: 00:30 **Over Time**: 02:00

Federal ID: Location:

Reviewer: Wilcox, Jason Approved Date: 01-Apr-10 Status: Approved

Weather

Temperature 7 AM 12 PM 4PM

Precipitation Condition Rain

Working Day | If no, explain:

Diary:

OBG Bolting & Welding

ABF crews came to the site at 6:45 AM. Crews had to work on E - 1 & E - 2 U ribs permanent bolts installations in the North wing , lower stiffeners , & South wing lower plates welding . Crews started at 7:00 AM.

Walter , & Jose had to work on the North wing U ribs (28 - 39) permanent bolt installations . Crews started at 7:10 AM. to sort their bolts , nuts , & washers . Crews were done at 7:20 AM. They had to remove the temporary bolts , & drift pins & install the proper length bolts . Crews were done at 3:15 PM. . Up to date all North side U ribs , but U ribs # 28 & 34 are completed .

At 2:00 PM. Obra , Matt , James , Pablo , & Jeffery came to work on E - 1 E - 2 U ribs connections middle section . Crews had to run air lines , sort their bolts for tomorrow . Crews were done at 3:15 PM.

Crews did not perform any work today . Only preparations . Crews had to wrap up their tools & equipment All bolting crews left at 3:25 PM.

Welding crews had to work on D 6, D 9, & D 10 vertical stiffeners. Crews had to grind the vertical stiffeners. They started at 7:20 AM. Crews were done at 7:50 AM.

Jordan had to work on D 9 . He started his 1st pass at 10:00 AM. He was done at 11:30 AM. Mitch started to weld D 10 at 8:00 AM. He was done at 11:15 AM. Mitch had to cut the 1st pass . Jordan , & Sangtao had to work with him . D 10 was completed on both sides . D 6 & D 9 were completed on one side only .

After that , Mitch had to work on D 6 . He started his 1st pass at 11:25 AM. Sangtao had to finish D 6 . He was done at 4:15 PM.

Jordan & Sangtao had to work with Mitch . They had to clean, grind , cut the ear plates for the remaining stiffners , & monitor the heat .

In addition to that, crews had to work with all other welding crews on the site.

Rory & Jeremy had to work on the lower plates on the South wing between stiffeners S 10 & S 19 . 2.5 meter long weld . Crews had to set the Bug - O machine . Crews started at 8:00 AM.

In addition to that, crews had to cover the heating unit system on the South wing. They had to wrap it with thermal blanket. Crews were done at 9:30 AM.

Rory started the 1st pass on the South wing plate at 10:15 AM. Rory & Jeremy had to cut the 1st pass. Rory resumd welding at 11:15 AM. At 12:00 PM. Crews completed 2 passes. At 3:00 PM. Crews completed 4 passes. At 5:00 PM. Crews had completed 5 passes. 2 more passe & the cover pass & that section is completed. Crews were done at 5:15 PM.

Jim , Tom , Bernie , Scott , michael , Dan , & Gary were on the site for all welding activities .

Earl, & lan had to work on the lower back bars for E - 3 & E - 4, & on the side back bars between

ddrRptbyBidItem

Page 1 of 2

Run date 21-Nov-14

3:43 PM

Time

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Daouk, Sami Diary #: 018 Date: 09-Mar-2010 Tuesday

 $E-2\ \&\ E-3$. Crews had to install the temporary adjustment brackets , place the back bars , & drive wedges to align the lower plates . Crews started at 7:15 AM. They were done at 10:30 AM.

After that , crews had to work on the side back bars between E - 2 & E - 3. Crews had to weld 4 brackets on the South side of the girder box , & on the bottom of the top plates on the North wing . They started at 11:00 AM. Crews were done at 5:15 PM. Bonifacio Daquinag was on the site with the crews .

Kenneth, & Chun had to work on the top plates. crews had grind the high spots for the 2nd day. They started at 8:00 AM. Crews was done at 5:10 PM. All welding crews left at 5:25 PM.

In the afternoon, Steven, Tom, & Dan had to UT the deck plates between 11.00 meter & 16.00 meter points. Steven found 2 spots to be repaired. Check Dan's report for more details.

04-0120F4	Bid Item: 056 E-L02-OBG.056 E Line Lift 02 OBG Erect structural steel						al steel	
AMERICAN BRID	OGE/FLUOR, A JV							
Labor								
Trade	Class	Name	RT Hrs	OT Hrs	DT Hrs	Total	Remarks	Dispute
Contractor:	AMERICAN BRIDGE/F	FLUOR, A JV						
Ironworker	JNM	Chun F	8.00	2.00	0.00	10.00		
Ironworker	JNM	WALTER HERNANDEZ	8.00	0.00	0.00	8.00		
Ironworker	APP	PABLO RAMIREZ	1.00	0.00	0.00	1.00		
Ironworker	JNM	OBRA PAULK	1.00	0.00	0.00	1.00		
Ironworker	JNM	MATTHEW HOLT	1.00	0.00	0.00	1.00		
Ironworker	JNM	JOSE AMAYA-MESA	8.00	0.00	0.00	8.00		
Ironworker	JNM	JIM CANTANDO	1.00	0.00	0.00	1.00		
Ironworker	APP	JEFFREY BRICKER	1.00	0.00	0.00	1.00		$\overline{\Box}$
Ironworker	JNM	SANGTAO HUANG	8.00	2.00	0.00	10.00		
Ironworker	FOR	RORY HOGAN	8.00	2.00	0.00	10.00		
Ironworker	JNM	MITCHELL SITTINGER	8.00	2.00	0.00	10.00		
Ironworker	APP	KENNETH CHAPTELL	8.00	2.00	0.00	10.00		
Ironworker	JNM	JORDAN HAZELAAR	8.00	2.00	0.00	10.00		
Ironworker	APP	JEREMY DOLMAN	8.00	2.00	0.00	10.00		
Equipment							Rental Company	
Equipment	ID Description		RT Hrs	OT Hrs	ST Hrs	IT Hrs	Remarks	Dispute
	AMERICAN BRIDGE/F	LUOR, A JV						•
002084	02084 WELDING MACHINE, MILLER						No	
		,	0.00	0.00	0.00	0.00		
002083	WELDING MA	CHINE, MILLER 250 AMP					No	
		,	0.00	0.00	0.00	0.00		
002082	WELDING MA	CHINE, MILLER 250 AMP					No	
			0.00	0.00	0.00	0.00		
*E0070562	WELDING EQ	UIPMENT					No	
			0.00	0.00	0.00	0.00		
*E0050562	WELDING EQ	JIPMENT	3.00	2.00	2.30	2.30	No	
2000002		-···-···	0.00	0.00	0.00	0.00		
			3.00	2.50	3.30	0.00		

